

Category: Airframe

Manufacturer: Raytheon Aircraft Co.

Model: MU-300

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
00-2001 R6 5/1/2007	Service Bulletin - General-Hawker Beechcraft Publications-What Is Available And How To Obtain It		informative only "Hawker" name change No Action Required	X			
00-3000 R1 9/1/1997	Service Bulletin - General-Publications- Information On The Introduction Of A New Service Bulletin Format And,Contd.		informative of SB Publication numbering system change No Action Required	X			
103570-21-4012 5/30/1995	AIR CONDITIONING--OUTFLOW/ SAFETY VALVE--IDENTIFICATION OF VALVES THAT REQUIRE REPLACEMENT			X			
11-001 6/5/1984	Service Bulletin - Pitot/Static Drain Markings			X			
11-002 R1 11/21/1985	Service Bulletin - Service Placards Installation			X			
11-003 R1 9/3/1991	Service Bulletin - Placard And Markings- Replacement Of Aft Facing Seat Information Placards	8/23/1993	Complied With	X			
21-001 3/28/1983	Service Bulletin - Air Conditioning Duct Material Change			X			
21-002 7/8/1983	Service Bulletin - Refrigeration Package Wiring Damage			X			
21-003 R1 1/13/1984	Service Bulletin - * Environmental Control Unit (Ecu)			X			
21-004 R1 1/18/1984	Service Bulletin - Pressure Regulator Valve Replacement			X			
21-005 1/13/1984	Service Bulletin - Emergency Pressurization Outlet			X			
21-006 10/28/1983	Service Bulletin - Cabin Over Pressure Switch Vent			X			
21-007 11/29/1983	Service Bulletin - Ecu Ejector S.O. Valve Operation			X			
21-008 5/14/1984	Service Bulletin - Temperature Sensor Mounting Replacement			X			
21-2461 R1 11/1/2001	Service Bulletin - Environmental/Air Conditioning-Cabin And Cockpit Temperature Sensor Blower Replacement			X			

Category: Airframe

Manufacturer: Raytheon Aircraft Co.

Model: MU-300

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
21-3862 6/1/2008	Service Bulletin - Air Conditioning-Duct Temperature Sensor Inspection And Replacement			X			
23-001 2/10/1983	Service Bulletin - Coax No. 1 And Coax No. 2 Cables Installed Too Close To Conditioned Air Duct			X			
23-002 1/24/1989	Service Bulletin - Auto Flight-Rewiring Of The Autopilot "Off" Annunciator	5/23/1989	Complied With	X			
24-001 8/25/1982	Service Bulletin - Replacement Of Generator Control Unit			X			
24-003 R1 3/13/1984	Service Bulletin - Power Distribution			X			
24-004 2/13/1984	Service Bulletin - Junction Panel Current Sensor Guard			X			
24-005 4/2/1984	Service Bulletin - Current Sensors (P/N 2sc1-X/ 2sc2-X)			X			
24-006 R1 10/15/1984	Service Bulletin - Standby Power Supply Modification			X			
24-007 8/24/1984	Service Bulletin - Replacement Of Emergency And Inverter No. 2 Relays			X			
24-008 6/10/1985	Service Bulletin - Current Sensor Screw			X			
24-009 9/15/1993	Service Bulletin - Replacement Of Current Sensors	10/27/1994	Complied With	X			
24-3693 2/1/2005	Service Bulletin - Electrical Power-Starter-Generator Shield Ground Relocation			X			
2476 R2 6/1/1997	Service Bulletin - *Alliedsignal-Environmental/ Air Conditioning-Outflow/Safety Valve Inspection/Replacement			X			
25-001 11/3/1982	Service Bulletin - Modification Of Barr/Galley Door (B-1/B-2)			X			
25-002 RA 2/15/1983	Service Bulletin - Interior Modification			X			

Category: Airframe

Manufacturer: Raytheon Aircraft Co.

Model: MU-300

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
25-003 8/10/1983	Service Bulletin - Rudder Pedal Heel Slip Panel			X			
25-004 9/6/1985	Service Bulletin - Standard Passenger Seat Lock			X			
25-2536 R2 3/1/2002	Equipment/furnishings-crew seat structure and seat track adjustment mechanism improvement	4/8/2002	Complied With Installed Kit P/N 128-5047-1	X			
25-3688 9/1/2005	Service Bulletin - Equipment/Furnishings-Cabin Swiveling Seat Replacement	5/30/2007	N/A Seat Not Installed	X			
25-3796 12/1/2006	Service Bulletin - *Ppi-Equipment/Furnishings-Ppi P/N 20918-59 And P/N 20918-63 Forward Closet Assembly Product Improvement			X			
2585 R1 8/1/1999	Service Bulletin - *Alliedsignal Sb - Environmental/Air Conditioning - Environmental Control System (Ecs),Contd.			X			
26-001 11/1/1984	Service Bulletin - Engine Fire Extinguisher Bottles			X			
26-3803 10/1/2006	Service Bulletin - Fire Protection-Inspection/ Replacement Of Meggit Thermistor Detectors	1/5/2007	N/A	X			
27-002 11/30/1983	Service Bulletin - Flap Follow-Up Switches			X			
27-003 R1 3/13/1984	Service Bulletin - Inspection And Repair Of The Pitch Trim Actuator Motor			X			
27-004 R1 3/13/1984	Service Bulletin - Flap Position Transmitters			X			
27-3229 3/1/1999	Service Bulletin - *Beech-Flight Controls-Inspection/Improvement Of Angle Of Attack Pressure Transducers	5/5/1983	N/A	X			
27-3579 R1 5/1/2005	Service Bulletin - Flight Controls-Spoiler Control Cable Turnbuckle Retention	11/3/2005	Complied With	X			
27-3805 11/1/2006	Service Bulletin - Flight Controls-Flap Hydraulic System Electrical Wiring Modification			X			
27-3827 3/1/2007	Service Bulletin - Flight Controls-Flap Asymmetry Detector Inspection And Replacement	5/30/2007	N/A Part Not Installed	X			

Category: Airframe

Manufacturer: Raytheon Aircraft Co.

Model: MU-300

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
28-001 11/21/1989	FUEL-PART 1, INSTALLATION OF A PLACARD ON THE FUEL FILLER DOOR; PART II, REPLACEMENT OF AFT FUSELAGE FUEL TANK FOAM			X			
30-001 RA 9/13/1983	Service Bulletin - Modifications Required For Operation In Known Icing Conditions			X			
30-002 6/27/1983	Service Bulletin - Modification Required For Operation In Known Icing Conditions - Placard Removal			X			
30-003 R1 5/17/1985	Service Bulletin - Windshield Wiper Blades			X			
30-004 10/1/1985	Service Bulletin - Horizontal Stabilizer Deice System Wiring			X			
30-005 10/1/1985	Service Bulletin - Safety Wire Application - H Stabilizer Deice Backup Switch			X			
30-006 6/14/1996	Service Bulletin - Ice And Rain Protection- Horizontal Stabilizer Anti-Ice System Inspection	8/3/1996	Complied With	X			
30-007 1/12/1996	ALTERNATE MEANS OF COMPLIANCE FOR AIRWORTHINESS DIRECTIVE AD 94-25-10, DATED DECEMBER 26, 1994, APPLICABLE TO,CONTD.	1/12/1995	Complied With	X			
32-001 RA 6/8/1983	Service Bulletin - Modification Of Ldg Position Indication			X			
32-002 3/16/1983	Service Bulletin - Change Cable Clamps On Emergency Gear Down Cable			X			
32-003 3/16/1983	Service Bulletin - Ground Safety Electrical System			X			
32-004 R2 6/1/1984	Service Bulletin - Correct Erroneous Part Number			X			
32-005 2/6/1984	Service Bulletin - * Retorque Of Mlg Downlock Release Cylinder Locknut			X			
32-006 9/13/1984	Service Bulletin - Mlg Door Shuttle Valve Elbow			X			
32-007 R2 10/31/1988	Service Bulletin - Mlg Shock Strut Cylinder Inspection/Repair	1/7/1987	Complied With	X			

Category: Airframe

Manufacturer: Raytheon Aircraft Co.

Model: MU-300

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
32-008 10/15/1985	Service Bulletin - Cylinder Inspection And Retorque			X			
32-009 1/2/1986	Service Bulletin - Main Landing Gear Trunnion Fitting			X			
32-010 3/24/1987	Service Bulletin - Nose Landing Gear Uplock Improvement			X			
32-011 9/2/1988	Service Bulletin - Main Landing Gear Up-Lock Mechanism Stopper Bolt - Safety Wire			X			
32-3120 9/1/1997	Service Bulletin - * Dowty Aerospace-Landing Gear-Brakemaster Cylinder Reowrk	12/6/1997	Complied With	X			
32-3300 12/1/1999	Service Bulletin - Landing Gear - Parking Brake Hydraulic Line Clamp Installation	5/5/1983	N/A	X			
32-3615 7/1/2005	Service Bulletin - Landing Gear-Hawker 800xp/1000 Mlg Sidestay Assembly Identification			X			
32-3696 7/1/2005	Service Bulletin - Landing Gear-Hawker 800xp/1000 Main Landing Gear (Mlg) Upper/Lower Arm And Sidestay Assembly Re-Identification			X			
32-3741 6/1/2006	Service Bulletin - Landing Gear-Nlg Aft Door Bonding Jumper Removal			X			
32-3873 2/1/2008	Service Bulletin - Landing Gear-Position Switch Inspection/Adjustment	3/7/2008	Complied With	X			
33-001 12/3/1982	Service Bulletin - Bonding And Finishing Of Nav Light Lightning Protector Strip, Lh & Rh Wing Tips			X			
34-001 8/17/1982	Service Bulletin - Wiring Change Of Ad650a Attitude Director Indicator (Adi)			X			
34-002 R1 1/13/1984	Service Bulletin - Resistor Change - No. 2 Flight Director			X			
34-003 R1 4/4/1984	Service Bulletin - Dual Adf Antenna Doubler			X			
34-004 R1 8/15/1985	Service Bulletin - Hsi Course/Heading Electrical Power Distribution			X			

Category: Airframe

Manufacturer: Raytheon Aircraft Co.

Model: MU-300

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
34-005 1/25/1986	Service Bulletin - Copilots Gyro Horizon			X			
34-006 9/15/1986	Service Bulletin - Avionics Indicator Panels Improvement			X			
34-3628 11/1/2003	Service Bulletin - Navigation-Installation Of Improved Pitot Probes			X			
35-001 RA 3/3/1983	Service Bulletin - Connection Of Mask To Portable Oxygen Cylinder			X			
35-002 R1 2/4/1986	Service Bulletin - Cabin Oxygen Mask Lid - Lanyard			X			
35-3333 3/1/2000	Service Bulletin - Oxygen-Oxygen Gage Face Plate Inspection/Modification	7/10/2001	N/A	X			
39-001 10/27/1982	Service Bulletin - Modification Of Gables Radio Control Panel. Addition Of Diode Between K2 Pin 2 And K3 Pin 2.			X			
39-002 5/30/1984	Service Bulletin - Hf Communication Relay Protection			X			
39-003 7/30/1991	Service Bulletin - Electrical Panels, Parts And Instruments-Ammeter System Modification	8/26/1993	Complie With	X			
400-189 R1 1/1/2002	Inspection-engine carry through mount bracket cracks			X			
52-001 3/15/1994	Service Bulletin - Doors-Emergency Exit Handle Hook Markings	3/2/1995	Complie With	X			
53-001 2/11/1983	Service Bulletin - Modification Of Pilot/Copilot Seat And Seat Stop			X			
53-002 2/10/1983	Service Bulletin - Replace Existing Pilot/Copilot Floorboards With Aluminum Floorboards			X			
53-3486 6/1/2003	Fuselage-installation of drain holes in the mixer bay panels	7/28/2003 8299.3	Complied with- Added one drain hole to mixer area cover.	X			
53-3559 5/1/2003	Service Bulletin - Fuselage-Corrosion Inspection/ Drilling Of Drain Hole In Fuselage Bulkhead Frame At Canted Fuselage Station,Contd.			X			

Category: Airframe

Manufacturer: Raytheon Aircraft Co.

Model: MU-300

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
53-3814 4/1/2007	Service Bulletin - Fuselage-Aft Fuselage Fuel Tank Structure Rivet Replacement			X			
54-001 11/8/1982	Service Bulletin - Inboard Nacelle Access Door Modification Both Lh And Rh Engines			X			
55-001 R1 11/1/1984	Service Bulletin - Horizontal Stabilizer Inspection Panels			X			
55-002 12/1/1987	Service Bulletin - Inspection And Modification Of Seal Fairing Of Vertical Stabilizer			X			
55-3428 R1 11/1/2002	Service Bulletin - Stabilizers-Horizontal Stabilizer Seal Plate Repair/ Replacement	5/31/2002	Complied With	X			
55-4071 3/1/2012	Service Bulletin - Stabilizers-Improved Horizontal Stabilizer Ribs			X			
57-001 8/17/1982	Service Bulletin - Installation Of Stiffener To Trailing Edge Assembly - Wing Middle			X			
57-3449 4/1/2002	Service Bulletin - Wings-Wing Bolt Replacement			X			
71-001 6/27/1985	Service Bulletin - Use Of Jt15d-4d Engines On Jt15d-4 Equipped Airplanes			X			
71-001 R2 6/1/1984	MU-300 performance enhancement package			X			
71-004 1/8/1992	POWER PLANT-REPLACEMENT OF ENGINE MOUNT BOLTS AND NUTS	12/22/1992	Complied With	X			
71-005 R1 10/7/1994	Service Bulletin - Engine Intake Duct Inner Skin Replacement	7/22/1994	Complied With	X			
71-006 8/27/1993	Service Bulletin - Replacement Of The Engine Oil Temperature Sensor	10/27/1994	Complied With	X			
71-3311 12/1/2000	Service Bulletin - Power Plant-Replacement Of The Engine Isolator Mounts	5/23/2002	Complied With L/H and R/H	X			
74-001 4/25/1986	STARTER RELAY REPLACEMENT			X			

Category: Airframe

Manufacturer: Raytheon Aircraft Co.

Model: MU-300

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
74-002 4/25/1986	STARTER RELAY REPLACEMENT			X			
76-001 5/6/1993	Service Bulletin - Improved Retention Of Thrust Reverser Power Lever Bearings	5/5/1983	N/A	X			
78-001 3/3/1983	Service Bulletin - Change Bolts Connecting Bypass Duct To The Engine Flange			X			
T-1A-0064 1/1/1999	Ice and rain protection- anti-ice system modification			X			

©ATP

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7001 R24 1/22/2009	Service Bulletin - Turbofan Engine-Approved Listing Of (Synthetic) Lubricating Oils			X			
7002 R42 5/11/2010	Service Bulletin - Turbofan Engine-Rotor Components-Service Lives			X			
7003 R36 2/18/2013	Service Bulletin - Turbofan Engine-Engine Operating Time Between Overhauls And Hot Section Inspection Frequency			X			
7003 R37 3/18/2014	Service Bulletin - Turbofan Engine-Engine Operating Time Between Overhauls And Hot Section Inspection Frequency			X			
7144 R20 9/23/2013	Service Bulletin - Turbofan Engine-Engine Fuels And Additives-Requirements And Approved Listing			X			
7150 R7 11/19/1991	Service Bulletin - Identification Of Engines Using Build Specifications			X			
7154 R1 3/28/1988	Service Bulletin - No. 4 Bearing Housing Cover Strainer Element Assembly - Introduction Of			X			
7165 R4 8/21/1991	Service Bulletin - Improved No. 2 Bearing Carbon Seal Assembly With Integral Nut-Introduction Of			X			
7182 R2 8/13/1992	Service Bulletin - Waspaloy Flange Bolts - Introduction Of			X			



Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7185 R2 4/20/1992	Service Bulletin - Oil Pump Assembly-Improved Oil Scavenging			X			
7187 R6 11/28/1996	Service Bulletin - Improved Centrifugal Impeller- Introduction Of			X			
7188 R2 5/21/1986	Service Bulletin - Cancelled-Superseded By Sb7232 And Sb7233			X			
7189 R3 10/26/1989	Service Bulletin - Superseded By Sb 7275			X			
7192 R2 7/27/1993	Service Bulletin - Turbofan Engine-Low Turbine Shaft-Improved Corrosion Resistance			X			
7193 R6 12/12/1996	Service Bulletin - Turbofan Engine-No. 4 Bearing Housing-Improved Method Of Bolt Retention			X			
7196 R1 9/6/1984	Service Bulletin - New Low Compressor Inner Shroud - Introduction Of			X			
7197 R1 10/9/1984	Service Bulletin - Improved Impeller Shroud Vibration Damper Ring - Introduction Of			X			
7199 R3 1/27/1992	Service Bulletin - Improved Combustion Chamber Liner Igniter Grommet- Introduction Of			X			
7200 R3 3/2/1993	Service Bulletin - Operation Of A Jt15d-4d Engine As A Jt15-4 Engine (Mitsubishi Aircraft Installation Only)			X			
7202 R1 4/15/1985	Service Bulletin - New Improved Low Turbine Rotor Blades - Introduction Of			X			
7205 2/28/1985	Service Bulletin - Engine Hot Nozzle Reclassification			X			
7206 R2 8/14/1992	Service Bulletin - New Improved No. 2 Bearing Retaining Plate-Introduction Of			X			
7207 R1 7/7/1986	Service Bulletin - Ignition Exciter To Igniter - Replacement Of			X			
7212 R2 10/27/1992	Service Bulletin - Lower Tower Shaft Bearing Antirotation Woodruff Key- Replacement Of-Superseded By P&Wc S.B. No. Jt15d-72-7329			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7215 R1 8/4/1993	Service Bulletin - Waspaloy Flange Bolts- Introduction Of			X			
7220 R3 3/17/1992	Service Bulletin - New No. 4 Bearing Oil Nozzle And Improved Bearing Cover- Introduction Of			X			
7226 R1 3/17/1992	Service Bulletin - Improved Turbine Shaft Locking Bolt-Replacement Of			X			
7229 R1 3/17/1992	Service Bulletin - Improved Breather Adapter- Introduction Of			X			
7230 R1 3/17/1992	Service Bulletin - Improved Centrifugal Breather Impeller Assembly-Introduction Of			X			
7232 R1 1/27/1988	Service Bulletin - Improved Gas Generator Diffuser Deflector Strip For Pre-Sb7262 And Post-Sb7217 Engines - Introduction Of			X			
7233 R1 9/28/1987	Service Bulletin - Improved Gas Generator Diffuser Deflector Strip For Pre-Sb7217 Engines - Introduction Of			X			
7236 R2 6/4/1990	Service Bulletin - Improved No. 1 Bearing Housing Assembly - Introduction Of			X			
7238 R2 10/26/1989	Service Bulletin - Improved No. 4 Bearing Housing Heatshield - Introduction Of (For Engines Incorporating Sb7193)			X			
7240 R1 4/21/1988	Service Bulletin - Improved Gas Generator Case - Introduction Of			X			
7244 R4 7/17/2000	Service Bulletin - Turbofan Engine-Low Turbine Disk And Turbine Shaft Assembly-Improved Durability			X			
7251 R4 3/17/1992	Service Bulletin - Oil Damped No. 4 Bearing- Introduction Of			X			
7252 R1 1/20/1992	Service Bulletin - Outer Bypass Duct-Installation Of Rivets To Improve Durability			X			
7253 R4 8/1/2001	Service Bulletin - Turbofan Engine-Deflector Support Ring-Improved Retention			X			
7254 R2 3/17/1992	Service Bulletin - Improved Centrifugal Impeller And High Compressor Shaft- Introduction Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7257 R2 7/2/1987	JT15D FAN BLADE INSPECTION - INTRODUCTION OF			X			
7259 R3 7/7/1992	Service Bulletin - Turbofan Engine-N1 Tacho Drive Bevel Gears-Replacement Of			X			
7261 R1 3/17/1992	Service Bulletin - Gas Generator Assembly No. 3 Bearing Oil Scavenge Tube- Modification Of			X			
7262 R3 3/17/1992	Service Bulletin - Gas Generator Case-Improved No. 3 Bearing Scavenge Tube And Reprofiled Diffuser Tubes- Introduction Of			X			
7263 R1 1/18/1989	Service Bulletin - Improved C Flange Bolts - Introduction Of			X			
7264 R2 5/8/1991	Service Bulletin - Low Compressor Stator Assembly-Improved Retention			X			
7265 R2 3/17/1992	Service Bulletin - Oil Pump Assembly-Introduction Of			X			
7268 R2 10/20/1992	Service Bulletin - Turbofan Engine-Low Compressor Case Dampening Ring- Introduction Of			X			
7269 R3 4/2/1992	Service Bulletin - Improved Accessory Gearbox Bevel Gears-Introduction Of			X			
7274 R1 6/6/1989	Service Bulletin - New Oil Filler Neck Assembly - Introduction Of			X			
7275 R1 1/19/1990	Service Bulletin - Improved Hot Section Hardware - Introduction Of			X			
7276 5/12/1989	Service Bulletin - Improved High Turbine Stator Assembly - Introduction Of			X			
7277 R4 10/7/1994	Service Bulletin - Improved Combustion Chamber Liner-Modification Of			X			
7286 R2 4/7/1993	Service Bulletin - Turbofan Engine-Gas Generator Case-Modification/Replacement Of			X			
7288 R3 5/27/1991	Service Bulletin - Improved Overspeed Control Wire Rope-Introduction Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7291 R3 10/20/1992	Service Bulletin - Turbofan Engine-Oil Check Valve Assembly- Replacement Of			X			
7292 9/25/1990	Service Bulletin - Improved Fuel Manifold Transfer Tube Locking Brackets - Introduction Of			X			
7293 R9 1/12/2005	Service Bulletin - Turbofan Engine-Improved High Turbine Rotor Blade (Directionally Solidified)- Introduction Of			X			
7294 R2 12/12/1996	Service Bulletin - Turbofan Engine-Improved Corrosion Resistance For High Turbine Shaft-Rework/ Replacement Of			X			
7296 R3 10/18/1991	TURBOFAN ENGINE-HIGH TURBINE STATOR ASSEMBLY (NICKEL)- REWORK/REPLACEMENT OF			X			
7297 R1 5/25/1991	TURBOFAN ENGINE-HIGH TURBINE BLADE CLASSIFIED RETAINING RIVETS-INTRODUCTION OF			X			
7300 R1 10/20/1992	Service Bulletin - Turbofan Engine-Vibration Damper Ring-Replacement Of			X			
7306 R1 12/6/1994	Service Bulletin - Suberceded By P & W C Sb 7384 R1-Turbofan Engine- Overspeed Control Linkage- Rework/Replacement Of			X			
7307 R2 12/19/1991	TURBOFAN ENGINE-HIGH TURBINE STATOR ASSEMBLY (COBALT)- REWORK OF			X			
7308 R1 10/15/1992	Service Bulletin - Turbofan Engine-No. 4 Bearing Housing Cover-Introduction Of Teflon Seal			X			
7309 R3 3/25/1998	Service Bulletin - Turbofan Engine-Overspeed Control Actuating Rod-Rework/ Replacement Of			X			
7311 R3 8/31/1998	Service Bulletin - Turbofan Engine-No. 1 Bearing-Replacement Of			X			
7313 7/28/1991	Service Bulletin - Turbofan Engine-Fan And Nose Cone Spacers-Replacement Of			X			
7317 R5 7/17/1998	Service Bulletin - Turbofan Engine-High Turbine Disk Assembly-Replacement/ Modification Of			X			
7318 R1 9/9/1993	Service Bulletin - Turbofan Engine-Low Compressor Shaft Assembly-Modification/ Replacement Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7319 R3 10/10/2002	Service Bulletin - Turbofan Engine-No. 4 Bearing Sleeve-Rework/Replacement Of			X			
7321 R2 3/10/1998	Service Bulletin - Turbofan Engine-Turbine, Second-Stage Stator Assembly- Replacement Of Spring Tension Washers			X			
7322 11/11/1991	Service Bulletin - Turbofan Engine-Rear Engine Mount Bolts-Replacement Of			X			
7324 R9 8/26/2004	Service Bulletin - Turbofan Engine-C Flange Bolts-Replacement Of			X			
7328 R1 3/18/1992	Service Bulletin - Turbofan Engine-Turbine, Third-Stage Stator Assembly- Replacement Of Spring Tension Washers			X			
7329 R2 3/2/1993	Service Bulletin - Accessory Gearbox Lower Tower Shaft Bearing-Rework/ Replacement Of-Supersedes P&Wc S.B. No. Jt15d-72-7212			X			
7330 R2 3/2/1993	Service Bulletin - Turbofan Engine-Intermediate Case Assembly-Rework/ Replacement Of			X			
7336 R1 10/19/1992	Service Bulletin - Turbofan Engine-Impeller Housing-Rework/Replacement Of			X			
7337 R5 10/3/2001	Service Bulletin - Turbofan Engine-Low Compressor Rotor Blade-Serialization			X			
7338 5/19/1992	Service Bulletin - Turbofan Engine-Oil Tank Cover -Rework/Replacement Of			X			
7340 R2 1/7/1994	Service Bulletin - Turbofan Engines-Combustion Chamber Liner Assemblies- Replacement/Modification Of			X			
7341 R1 11/12/1992	Service Bulletin - Turbofan Engine-Second Stage Turbine Stator Assembly- Replacement Of			X			
7344 R1 3/30/2010	Service Bulletin - Turbofan Engine-Intermediate Case Assembly-Replacement Of Studs At Flange A			X			
7345 10/29/1992	Service Bulletin - Turbofan Engine-Engine Shipping Container Assembly- Rework/Replacement Of			X			
7347 R1 7/10/1992	Service Bulletin - Turbofan Engine-Fcu/Fdv Interconnect Rod-Addition Of Washers			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7349 R1 12/12/1996	Service Bulletin - Turbofan Engine-Centrifugal Impeller-Replacement Of			X			
7350 R2 12/14/1994	Service Bulletin - No. 2 Bearing-Replacement Of			X			
7351 R6 4/27/2004	Service Bulletin - Turbofan Engine-Oil Tank Cover Assembly-Replacement/ Modification Of			X			
7355 R2 12/14/1994	Service Bulletin - No. 3 Bearing-Replacement Of			X			
7356 7/7/1992	Service Bulletin - Turbofan Engine-Second Stage Turbine Stator Assembly- Replacement Of			X			
7362 R3 4/17/1998	Service Bulletin - Turbofan Engine-Intershaft Oil Transfer Tube Assembly- Replacement Of			X			
7363 R1 7/7/1993	Service Bulletin - Third-Stage Turbine Stator Assembly-Replacement/ Modification Of			X			
7366 10/29/1992	Service Bulletin - Turbofan Engine-Exhaust Duct Flange Heat Shield-Replacement Of			X			
7369 R2 11/30/1994	Service Bulletin - Low Compressor Stator/Case Assembly-Improved Retention			X			
7375 R2 11/11/1994	Service Bulletin - Turbofan Engines-Single Ignition Exciter-Modification/ Replacement Of			X			
7376 11/3/1993	Service Bulletin - New Attachment Hardware For Diffuser Exit Duct Deflector Segments-Introduction Of			X			
7378 R1 11/11/1994	Service Bulletin - Accessory Gearbox Bearing Retaining Plate Bolts- Replacement Of			X			
7381 11/19/1993	Service Bulletin - Low Turbine Stator Support Assembly-Replacement/ Modification Of			X			
7384 R5 3/12/1998	Service Bulletin - Turbofan Engine-No.4 Bearing Housing Cover And Overspeed Control Bracket-Replacement/ Modification Of			X			
7385 R3 12/15/2005	Service Bulletin - Turbofan Engine-Outer Bypass Duct Assembly-Replacement Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7387 R2 11/27/1996	Service Bulletin - Turbofan Engine-Dual Ignition Exciter System Components- Replacement Of			X			
7390 3/1/1994	Service Bulletin - Low Turbine Shaft Assy., Low Compressor Shaft Assy. And Compressor Inlet Cone Shaft- Replacement Of			X			
7391 R1 11/11/1994	Service Bulletin - Inner Front Compressor Stator Assembly- Replacement Of			X			
7392 R1 11/11/1994	Service Bulletin - High Turbine Shaft- Modification/ Replacement Of			X			
7394 R2 11/11/1994	Service Bulletin - Asbestos-Free Fiber Gaskets- Introduction Of			X			
7395 10/25/1993	Service Bulletin - Trim Balancing Rivets- Introduction Of			X			
7399 R2 11/11/1994	Service Bulletin - High Turbine Baffle Assembly- Replacement Of			X			
7407 R1 11/11/1994	Service Bulletin - High Compressor Impeller And Shaft Set- Introduction Of			X			
7408 8/30/1993	Service Bulletin - No. 3 Bearing Air Seal Gasket- Replacement Of			X			
7409 9/2/1993	Service Bulletin - Classified Air Seal Spacers- Introduction/ Modification Of			X			
7410 R6 3/20/2009	Service Bulletin - Turbofan Engine-Outer Bypass Duct Assembly- Replacement/ Modification Of			X			
7411 R2 10/18/1999	Service Bulletin - Igniter And Fuel Nozzle Grommet Housing Assemblies- Replacement Of			X			
7414 11/5/1993	Service Bulletin - Low Compressor Rotor Hub- Replacement Of			X			
7419 12/8/1993	Service Bulletin - Intermediate Case Borescope Plain Cover- Replacement Of			X			
7421 3/9/1994	Service Bulletin - Packings For Oil Check Valve Assemblies- Replacement/ Modification Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7424 12/21/1993	Service Bulletin - Machine Key-Replacement Of			X			
7425 5/12/1994	Service Bulletin - Turbine Exhaust Duct Assembly- Replacement Of			X			
7426 R2 4/6/2005	Service Bulletin - Turbofan Engine- Low Turbine Stator Assembly- Introduction Of			X			
7428 R1 3/29/1995	Service Bulletin - Key Washer-Replacement Of			X			
7429 R4 4/21/2003	Service Bulletin - Turbofan Engine-Single And Dual Ignition System- Components-Replacement Of			X			
7430 12/12/1996	Service Bulletin - Turbofan Engine-Intermediate Case Assembly-Replacement Of			X			
7431 R3 1/8/1997	Service Bulletin - Turbofan Engine-Single Ignition Exciter System Components-Replacement Of			X			
7432 3/15/1994	Service Bulletin - High Turbine Interstage Metal Seal Ring-Replacement Of			X			
7438 R2 6/14/2001	Service Bulletin - Turbofan Engine-Rear Engine Mount Bracket Assembly- Replacement Of			X			
7442 6/28/1994	Service Bulletin - Overspeed Control Actuating Rod-Replacement Of			X			
7452 R4 4/29/2005	Service Bulletin - Turbofan Engine-Low Compressor Shaft Assembly, Intershaft Oil Transfer Tube Assembly And Turbine Shaft Locking, Contd.			X			
7457 R1 1/11/2007	Service Bulletin - Turbofan Engine-Single Ignition Exciter-Replacement/ Modification Of			X			
7459 R2 3/31/2011	Service Bulletin - Turbofan Engine-Igniter- Replacement Of			X			
7460 1/6/1995	Service Bulletin - Single And Dual Ignition Exciter-Replacement/ Modification Of			X			
7465 3/29/1995	Service Bulletin - No. 1 Bearing Front, Air Seal- Replacement/Modification			X			



Category: Engine

Manufacturer: Pratt &amp; Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7476 R1 12/14/2001	Service Bulletin - Turbofan Engine-Oil Filter Element-Replacement Of			X			
7482 R3 5/26/1997	Service Bulletin - Turbofan Engine-Single And Dual Ignition Exciter-Replacement/Modification Of			X			
7483 R2 11/27/1996	Service Bulletin - Turbofan Engine-Single And Dual Ignition Exciter-Replacement/Modification Of			X			
7484 R6 11/19/2004	Service Bulletin - Turbofan Engine-No.2 And No.3 Bearings-Replacement Of			X			
7487 R1 3/18/1997	Service Bulletin - Turbofan Engine-Oil Filler Neck Assembly-Replacement Of			X			
7488 R1 3/30/1998	Service Bulletin - Turbofan Engine-Low Turbine Rotor Disk-Replacement Of			X			
7504 9/28/1998	Service Bulletin - Turbine Engine-Conversion Of Jt15d-4d Engine To Jt15d-4b Configuration			X			
7507 9/26/1996	Service Bulletin - Turbofan Engine-Accessory Drive Covers-Replacement Of			X			
7508 R1 11/15/1996	Service Bulletin - Turbofan Engine-High Turbine Blade Lean-Inspection Of			X			
7509 7/8/1996	Service Bulletin - Turbofan Engine-Gas Generator Case-Modification Of			X			
7510 R2 2/26/1997	Service Bulletin - Turbofan Engine-Ignition Exciter-Replacement Of			X			
7513 R4 2/13/2009	Service Bulletin - Turbofan Engine-High And Low Pressure Turbine Nuts-Replacement Of			X			
7514 R1 2/24/1999	Service Bulletin - Turbofan Engine-Gas Generator Case-Modification/Replacement Of			X			
7515 R3 5/26/2003	Service Bulletin - Turbofan Engine-Outer Combustion Chamber Liner Wrapper Assembly-Replacement Of			X			
7517 R5 2/11/2009	Service Bulletin - Turbofan Engine-T5 Sensor By-Pass Duct Boss			X			

Category: Engine

Manufacturer: Pratt &amp; Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7522 R5 7/18/2007	Service Bulletin - Turbofan Engine-Gas Generator Case-Modification Of			X			
7523 2/12/1997	Service Bulletin - Turbofan Engine-Gas Generator Case-Replacement			X			
7528 11/14/1996	Service Bulletin - Turbofan Engine-No.2 Bearing Rotor Air Seal			X			
7530 R1 1/30/1997	Service Bulletin - Turbofan Engine-Number Three And A Half Bearing Oil Transfer Tube-Replacement Of			X			
7531 R1 2/3/1998	Service Bulletin - Turbofan Engine-T6 Immersion Thermocouple-Replacement Of			X			
7537 R2 3/4/1998	Service Bulletin - *Unison Product Information Letter-Turbofan Engine-Igniter Plugs-Replacement Of			X			
7540 2/17/1997	Service Bulletin - Turbofan Engine-Identification Support Plate-Replacement Of			X			
7541 2/24/1997	Service Bulletin - Turbofan Engine-Upper Towershaft Bearing Housing- Replacement Of			X			
7548 11/4/1997	Service Bulletin - Turbofan Engine-Oil Pump Assy- Replacement/Modification Of			X			
7549 R1 9/25/1997	Service Bulletin - Turbofan Engine-Gearbox Input Drive Spacer-Replacement Of			X			
7564 5/6/1999	Service Bulletin - Turbofan Engine-Towershaft- Replacement Of			X			
7565 5/5/1999	Service Bulletin - Turbofan Engine-Upper Tower Shaft Duplex Bearing- Replacement Of			X			
7567 R1 7/7/2000	Service Bulletin - Turbofan Engine-Igniter Box Grounding Strap-Introduction Of			X			
7577 7/12/2001	Service Bulletin - Turbofan Engine-Lower Lcf Life Impellers-Introduction Of			X			
7581 7/15/2002	Service Bulletin - Turbofan Engine-Introduction Of New Non-Cleanable Filter Element Option			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7585 7/5/2002	Service Bulletin - Turbofan Engine-Fuel Control Unit-Replacement Of			X			
7588 R2 1/24/2013	Service Bulletin - Turbofan Engine-Accessory Gearbox Input Drive Gear- Replacement/Modification Of			X			
7589 R1 5/15/2003	Service Bulletin - Turbofan Engine-High Turbine Disc Balancing Assembly- Replacement Of			X			
7601 2/16/2005	Service Bulletin - Turbofan Engine- New Protective Shipping Closure-Introduction Of			X			
7607 11/9/2006	Service Bulletin - Turbofan Engine-Fuel Control Ratio Lever-Inspection Of			X			
7618 R1 3/6/2008	Service Bulletin - Turbofan Engine-No. 4 Bearing Sleeve, Housing Assembly And Rotor Air Seal- Replacement/Modification Of			X			
7620 4/18/2008	Service Bulletin - Turbofan Engine-Low Pressure Turbine Disk-Inspection/ Replacement Of			X			
7623 R1 3/5/2009	Service Bulletin - Turbofan Engine-High Turbine Shaft-Replacement/Modification Of			X			
7625 R1 11/26/2010	Service Bulletin - Turbofan Engine-Gasket- Replacement Of			X			
7627 3/5/2012	Service Bulletin - Turbofan Engine-Low Pressure Turbine Interstage Rotor Air Seal And Rotor Air Seal- Replacement Of			X			
7633 9/24/2012	Service Bulletin - Turbofan Engine-Retaining Ring-Alternate Source			X			
A7614 10/23/2007	Service Bulletin - Turbofan Engine-Igniters- Inspection Of			X			

©ATP

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7001 R24 1/22/2009	Service Bulletin - Turbofan Engine-Approved Listing Of (Synthetic) Lubricating Oils			X			

Category: Engine

Manufacturer: Pratt &amp; Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7002 R42 5/11/2010	Service Bulletin - Turbofan Engine-Rotor Components-Service Lives			X			
7003 R36 2/18/2013	Service Bulletin - Turbofan Engine-Engine Operating Time Between Overhauls And Hot Section Inspection Frequency			X			
7003 R37 3/18/2014	Service Bulletin - Turbofan Engine-Engine Operating Time Between Overhauls And Hot Section Inspection Frequency			X			
7144 R20 9/23/2013	Service Bulletin - Turbofan Engine-Engine Fuels And Additives-Requirements And Approved Listing			X			
7150 R7 11/19/1991	Service Bulletin - Identification Of Engines Using Build Specifications			X			
7154 R1 3/28/1988	Service Bulletin - No. 4 Bearing Housing Cover Strainer Element Assembly - Introduction Of			X			
7165 R4 8/21/1991	Service Bulletin - Improved No. 2 Bearing Carbon Seal Assembly With Integral Nut-Introduction Of			X			
7182 R2 8/13/1992	Service Bulletin - Waspaloy Flange Bolts - Introduction Of			X			
7185 R2 4/20/1992	Service Bulletin - Oil Pump Assembly-Improved Oil Scavenging			X			
7187 R6 11/28/1996	Service Bulletin - Improved Centrifugal Impeller- Introduction Of			X			
7188 R2 5/21/1986	Service Bulletin - Cancelled-Superseded By Sb7232 And Sb7233			X			
7189 R3 10/26/1989	Service Bulletin - Superseded By Sb 7275			X			
7192 R2 7/27/1993	Service Bulletin - Turbofan Engine-Low Turbine Shaft-Improved Corrosion Resistance			X			
7193 R6 12/12/1996	Service Bulletin - Turbofan Engine-No. 4 Bearing Housing-Improved Method Of Bolt Retention			X			
7196 R1 9/6/1984	Service Bulletin - New Low Compressor Inner Shroud - Introduction Of			X			

Category: Engine

Manufacturer: Pratt &amp; Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7197 R1 10/9/1984	Service Bulletin - Improved Impeller Shroud Vibration Damper Ring - Introduction Of			X			
7199 R3 1/27/1992	Service Bulletin - Improved Combustion Chamber Liner Igniter Grommet- Introduction Of			X			
7200 R3 3/2/1993	Service Bulletin - Operation Of A Jt15d-4d Engine As A Jt15-4 Engine (Mitsubishi Aircraft Installation Only)			X			
7202 R1 4/15/1985	Service Bulletin - New Improved Low Turbine Rotor Blades - Introduction Of			X			
7205 2/28/1985	Service Bulletin - Engine Hot Nozzle Reclassification			X			
7206 R2 8/14/1992	Service Bulletin - New Improved No. 2 Bearing Retaining Plate-Introduction Of			X			
7207 R1 7/7/1986	Service Bulletin - Ignition Exciter To Igniter - Replacement Of			X			
7212 R2 10/27/1992	Service Bulletin - Lower Tower Shaft Bearing Antirotation Woodruff Key- Replacement Of-Superseded By P&Wc S.B. No. Jt15d-72-7329			X			
7215 R1 8/4/1993	Service Bulletin - Waspaloy Flange Bolts- Introduction Of			X			
7220 R3 3/17/1992	Service Bulletin - New No. 4 Bearing Oil Nozzle And Improved Bearing Cover- Introduction Of			X			
7226 R1 3/17/1992	Service Bulletin - Improved Turbine Shaft Locking Bolt-Replacement Of			X			
7229 R1 3/17/1992	Service Bulletin - Improved Breather Adapter- Introduction Of			X			
7230 R1 3/17/1992	Service Bulletin - Improved Centrifugal Breather Impeller Assembly-Introduction Of			X			
7232 R1 1/27/1988	Service Bulletin - Improved Gas Generator Diffuser Deflector Strip For Pre-Sb7262 And Post-Sb7217 Engines - Introduction Of			X			
7233 R1 9/28/1987	Service Bulletin - Improved Gas Generator Diffuser Deflector Strip For Pre-Sb7217 Engines - Introduction Of			X			

Category: Engine

Manufacturer: Pratt &amp; Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7236 R2 6/4/1990	Service Bulletin - Improved No. 1 Bearing Housing Assembly - Introduction Of			X			
7238 R2 10/26/1989	Service Bulletin - Improved No. 4 Bearing Housing Heatshield - Introduction Of (For Engines Incorporating Sb7193)			X			
7240 R1 4/21/1988	Service Bulletin - Improved Gas Generator Case - Introduction Of			X			
7244 R4 7/17/2000	Service Bulletin - Turbofan Engine-Low Turbine Disk And Turbine Shaft Assembly-Improved Durability			X			
7251 R4 3/17/1992	Service Bulletin - Oil Damped No. 4 Bearing- Introduction Of			X			
7252 R1 1/20/1992	Service Bulletin - Outer Bypass Duct-Installation Of Rivets To Improve Durability			X			
7253 R4 8/1/2001	Service Bulletin - Turbofan Engine-Deflector Support Ring-Improved Retention			X			
7254 R2 3/17/1992	Service Bulletin - Improved Centrifugal Impeller And High Compressor Shaft- Introduction Of			X			
7257 R2 7/2/1987	JT15D FAN BLADE INSPECTION - INTRODUCTION OF			X			
7259 R3 7/7/1992	Service Bulletin - Turbofan Engine-N1 Tacho Drive Bevel Gears-Replacement Of			X			
7261 R1 3/17/1992	Service Bulletin - Gas Generator Assembly No. 3 Bearing Oil Scavenge Tube- Modification Of			X			
7262 R3 3/17/1992	Service Bulletin - Gas Generator Case-Improved No. 3 Bearing Scavenge Tube And Refilled Diffuser Tubes- Introduction Of			X			
7263 R1 1/18/1989	Service Bulletin - Improved C Flange Bolts - Introduction Of			X			
7264 R2 5/8/1991	Service Bulletin - Low Compressor Stator Assembly-Improved Retention			X			
7265 R2 3/17/1992	Service Bulletin - Oil Pump Assembly-Introduction Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7268 R2 10/20/1992	Service Bulletin - Turbofan Engine-Low Compressor Case Dampening Ring-Introduction Of			X			
7269 R3 4/2/1992	Service Bulletin - Improved Accessory Gearbox Bevel Gears-Introduction Of			X			
7274 R1 6/6/1989	Service Bulletin - New Oil Filler Neck Assembly - Introduction Of			X			
7275 R1 1/19/1990	Service Bulletin - Improved Hot Section Hardware - Introduction Of			X			
7276 5/12/1989	Service Bulletin - Improved High Turbine Stator Assembly - Introduction Of			X			
7277 R4 10/7/1994	Service Bulletin - Improved Combustion Chamber Liner-Modification Of			X			
7286 R2 4/7/1993	Service Bulletin - Turbofan Engine-Gas Generator Case-Modification/Replacement Of			X			
7288 R3 5/27/1991	Service Bulletin - Improved Overspeed Control Wire Rope-Introduction Of			X			
7291 R3 10/20/1992	Service Bulletin - Turbofan Engine-Oil Check Valve Assembly- Replacement Of			X			
7292 9/25/1990	Service Bulletin - Improved Fuel Manifold Transfer Tube Locking Brackets - Introduction Of			X			
7293 R9 1/12/2005	Service Bulletin - Turbofan Engine-Improved High Turbine Rotor Blade (Directionally Solidified)- Introduction Of			X			
7294 R2 12/12/1996	Service Bulletin - Turbofan Engine-Improved Corrosion Resistance For High Turbine Shaft-Rework/ Replacement Of			X			
7296 R3 10/18/1991	TURBOFAN ENGINE-HIGH TURBINE STATOR ASSEMBLY (NICKEL)-REWORK/REPLACEMENT OF			X			
7297 R1 5/25/1991	TURBOFAN ENGINE-HIGH TURBINE BLADE CLASSIFIED RETAINING RIVETS-INTRODUCTION OF			X			
7300 R1 10/20/1992	Service Bulletin - Turbofan Engine-Vibration Damper Ring-Replacement Of			X			

Category: Engine

Manufacturer: Pratt &amp; Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7306 R1 12/6/1994	Service Bulletin - Suberceded By P & W C Sb 7384 R1-Turbofan Engine- Overspeed Control Linkage- Rework/Replacement Of			X			
7307 R2 12/19/1991	TURBOFAN ENGINE-HIGH TURBINE STATOR ASSEMBLY (COBALT)-REWORK OF			X			
7308 R1 10/15/1992	Service Bulletin - Turbofan Engine-No. 4 Bearing Housing Cover-Introduction Of Teflon Seal			X			
7309 R3 3/25/1998	Service Bulletin - Turbofan Engine-Overspeed Control Actuating Rod-Rework/ Replacement Of			X			
7311 R3 8/31/1998	Service Bulletin - Turbofan Engine-No. 1 Bearing-Replacement Of			X			
7313 7/28/1991	Service Bulletin - Turbofan Engine-Fan And Nose Cone Spacers-Replacement Of			X			
7317 R5 7/17/1998	Service Bulletin - Turbofan Engine-High Turbine Disk Assembly-Replacement/ Modification Of			X			
7318 R1 9/9/1993	Service Bulletin - Turbofan Engine-Low Compressor Shaft Assembly-Modification/ Replacement Of			X			
7319 R3 10/10/2002	Service Bulletin - Turbofan Engine-No. 4 Bearing Sleeve-Rework/Replacement Of			X			
7321 R2 3/10/1998	Service Bulletin - Turbofan Engine-Turbine, Second-Stage Stator Assembly- Replacement Of Spring Tension Washers			X			
7322 11/11/1991	Service Bulletin - Turbofan Engine-Rear Engine Mount Bolts-Replacement Of			X			
7324 R9 8/26/2004	Service Bulletin - Turbofan Engine-C Flange Bolts-Replacement Of			X			
7328 R1 3/18/1992	Service Bulletin - Turbofan Engine-Turbine, Third-Stage Stator Assembly- Replacement Of Spring Tension Washers			X			
7329 R2 3/2/1993	Service Bulletin - Accessory Gearbox Lower Tower Shaft Bearing-Rework/ Replacement Of-Supersedes P&Wc S.B. No. Jt15d-72-7212			X			
7330 R2 3/2/1993	Service Bulletin - Turbofan Engine-Intermediate Case Assembly-Rework/ Replacement Of			X			



Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7336 R1 10/19/1992	Service Bulletin - Turbofan Engine-Impeller Housing-Rework/Replacement Of			X			
7337 R5 10/3/2001	Service Bulletin - Turbofan Engine-Low Compressor Rotor Blade-Serialization			X			
7338 5/19/1992	Service Bulletin - Turbofan Engine-Oil Tank Cover -Rework/Replacement Of			X			
7340 R2 1/7/1994	Service Bulletin - Turbofan Engines-Combustion Chamber Liner Assemblies- Replacement/Modification Of			X			
7341 R1 11/12/1992	Service Bulletin - Turbofan Engine-Second Stage Turbine Stator Assembly- Replacement Of			X			
7344 R1 3/30/2010	Service Bulletin - Turbofan Engine-Intermediate Case Assembly-Replacement Of Studs At Flange A			X			
7345 10/29/1992	Service Bulletin - Turbofan Engine-Engine Shipping Container Assembly- Rework/Replacement Of			X			
7347 R1 7/10/1992	Service Bulletin - Turbofan Engine-Fcu/Fdv Interconnect Rod-Addition Of Washers			X			
7349 R1 12/12/1996	Service Bulletin - Turbofan Engine-Centrifugal Impeller-Replacement Of			X			
7350 R2 12/14/1994	Service Bulletin - No. 2 Bearing-Replacement Of			X			
7351 R6 4/27/2004	Service Bulletin - Turbofan Engine-Oil Tank Cover Assembly-Replacement/ Modification Of			X			
7355 R2 12/14/1994	Service Bulletin - No. 3 Bearing-Replacement Of			X			
7356 7/7/1992	Service Bulletin - Turbofan Engine-Second Stage Turbine Stator Assembly- Replacement Of			X			
7362 R3 4/17/1998	Service Bulletin - Turbofan Engine-Intershaft Oil Transfer Tube Assembly- Replacement Of			X			
7363 R1 7/7/1993	Service Bulletin - Third-Stage Turbine Stator Assembly-Replacement/ Modification Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7366 10/29/1992	Service Bulletin - Turbofan Engine-Exhaust Duct Flange Heat Shield-Replacement Of			X			
7369 R2 11/30/1994	Service Bulletin - Low Compressor Stator/Case Assembly-Improved Retention			X			
7375 R2 11/11/1994	Service Bulletin - Turbofan Engines-Single Ignition Exciter-Modification/ Replacement Of			X			
7376 11/3/1993	Service Bulletin - New Attachment Hardware For Diffuser Exit Duct Deflector Segments-Introduction Of			X			
7378 R1 11/11/1994	Service Bulletin - Accessory Gearbox Bearing Retaining Plate Bolts- Replacement Of			X			
7381 11/19/1993	Service Bulletin - Low Turbine Stator Support Assembly-Replacement/ Modification Of			X			
7384 R5 3/12/1998	Service Bulletin - Turbofan Engine-No.4 Bearing Housing Cover And Overspeed Control Bracket-Replacement/ Modification Of			X			
7385 R3 12/15/2005	Service Bulletin - Turbofan Engine-Outer Bypass Duct Assembly-Replacement Of			X			
7387 R2 11/27/1996	Service Bulletin - Turbofan Engine-Dual Ignition Exciter System Components- Replacement Of			X			
7390 3/1/1994	Service Bulletin - Low Turbine Shaft Assy., Low Compressor Shaft Assy. And Compressor Inlet Cone Shaft- Replacement Of			X			
7391 R1 11/11/1994	Service Bulletin - Inner Front Compressor Stator Assembly-Replacement Of			X			
7392 R1 11/11/1994	Service Bulletin - High Turbine Shaft- Modification/Replacement Of			X			
7394 R2 11/11/1994	Service Bulletin - Asbestos-Free Fiber Gaskets- Introduction Of			X			
7395 10/25/1993	Service Bulletin - Trim Balancing Rivets- Introduction Of			X			
7399 R2 11/11/1994	Service Bulletin - High Turbine Baffle Assembly- Replacement Of			X			

Category: Engine

Manufacturer: Pratt &amp; Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7407 R1 11/11/1994	Service Bulletin - High Compressor Impeller And Shaft Set-Introduction Of			X			
7408 8/30/1993	Service Bulletin - No. 3 Bearing Air Seal Gasket- Replacement Of			X			
7409 9/2/1993	Service Bulletin - Classified Air Seal Spacers- Introduction/Modification Of			X			
7410 R6 3/20/2009	Service Bulletin - Turbofan Engine-Outer Bypass Duct Assembly-Replacement/ Modification Of			X			
7411 R2 10/18/1999	Service Bulletin - Igniter And Fuel Nozzle Grommet Housing Assemblies- Replacement Of			X			
7414 11/5/1993	Service Bulletin - Low Compressor Rotor Hub- Replacement Of			X			
7419 12/8/1993	Service Bulletin - Intermediate Case Borescope Plain Cover-Replacement Of			X			
7421 3/9/1994	Service Bulletin - Packings For Oil Check Valve Assemblies-Replacement/ Modification Of			X			
7424 12/21/1993	Service Bulletin - Machine Key-Replacement Of			X			
7425 5/12/1994	Service Bulletin - Turbine Exhaust Duct Assembly- Replacement Of			X			
7426 R2 4/6/2005	Service Bulletin - Turbofan Engine- Low Turbine Stator Assembly- Introduction Of			X			
7428 R1 3/29/1995	Service Bulletin - Key Washer-Replacement Of			X			
7429 R4 4/21/2003	Service Bulletin - Turbofan Engine-Single And Dual Ignition System- Components-Replacement Of			X			
7430 12/12/1996	Service Bulletin - Turbofan Engine-Intermediate Case Assembly-Replacement Of			X			
7431 R3 1/8/1997	Service Bulletin - Turbofan Engine-Single Ignition Exciter System Components-Replacement Of			X			

Category: Engine

Manufacturer: Pratt &amp; Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7432 3/15/1994	Service Bulletin - High Turbine Interstage Metal Seal Ring-Replacement Of			X			
7438 R2 6/14/2001	Service Bulletin - Turbofan Engine-Rear Engine Mount Bracket Assembly-Replacement Of			X			
7442 6/28/1994	Service Bulletin - Overspeed Control Actuating Rod-Replacement Of			X			
7452 R4 4/29/2005	Service Bulletin - Turbofan Engine-Low Compressor Shaft Assembly, Intershaft Oil Transfer Tube Assembly And Turbine Shaft Locking,Contd.			X			
7457 R1 1/11/2007	Service Bulletin - Turbofan Engine-Single Ignition Exciter-Replacement/ Modification Of			X			
7459 R2 3/31/2011	Service Bulletin - Turbofan Engine-Igniter-Replacement Of			X			
7460 1/6/1995	Service Bulletin - Single And Dual Ignition Exciter-Replacement/ Modification Of			X			
7465 3/29/1995	Service Bulletin - No. 1 Bearing Front, Air Seal- Replacement/Modification			X			
7476 R1 12/14/2001	Service Bulletin - Turbofan Engine-Oil Filter Element-Replacement Of			X			
7482 R3 5/26/1997	Service Bulletin - Turbofan Engine-Single And Dual Ignition Exciter-Replacement/Modification Of			X			
7483 R2 11/27/1996	Service Bulletin - Turbofan Engine-Single And Dual Ignition Exciter-Replacement/Modification Of			X			
7484 R6 11/19/2004	Service Bulletin - Turbofan Engine-No.2 And No.3 Bearings-Replacement Of			X			
7487 R1 3/18/1997	Service Bulletin - Turbofan Engine-Oil Filler Neck Assesmbly-Replacement Of			X			
7488 R1 3/30/1998	Service Bulletin - Turbofan Engine-Low Turbine Rotor Disk-Replacement Of			X			
7504 9/28/1998	Service Bulletin - Turbine Engine-Conversion Of Jt15d-4d Engine To Jt15d-4b Configuration			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7507 9/26/1996	Service Bulletin - Turbofan Engine-Accessory Drive Covers-Replacement Of			X			
7508 R1 11/15/1996	Service Bulletin - Turbofan Engine-High Turbine Blade Lean-Inspection Of			X			
7509 7/8/1996	Service Bulletin - Turbofan Engine-Gas Generator Case-Modification Of			X			
7510 R2 2/26/1997	Service Bulletin - Turbofan Engine-Ignition Exciter-Replacement Of			X			
7513 R4 2/13/2009	Service Bulletin - Turbofan Engine-High And Low Pressure Turbine Nuts- Replacement Of			X			
7514 R1 2/24/1999	Service Bulletin - Turbofan Engine-Gas Generator Case-Modification/Replacement Of			X			
7515 R3 5/26/2003	Service Bulletin - Turbofan Engine-Outer Combustion Chamber Liner Wrapper Assembly-Replacement Of			X			
7517 R5 2/11/2009	Service Bulletin - Turbofan Engine-T5 Sensor By-Pass Duct Boss			X			
7522 R5 7/18/2007	Service Bulletin - Turbofan Engine-Gas Generator Case-Modification Of			X			
7523 2/12/1997	Service Bulletin - Turbofan Engine-Gas Generator Case-Replacement			X			
7528 11/14/1996	Service Bulletin - Turbofan Engine-No.2 Bearing Rotor Air Seal			X			
7530 R1 1/30/1997	Service Bulletin - Turbofan Engine-Number Three And A Half Bearing Oil Transfer Tube-Replacement Of			X			
7531 R1 2/3/1998	Service Bulletin - Turbofan Engine-T6 Immersion Thermocouple-Replacement Of			X			
7537 R2 3/4/1998	Service Bulletin - *Unison Product Information Letter-Turbofan Engine-Igniter Plugs-Replacement Of			X			
7540 2/17/1997	Service Bulletin - Turbofan Engine-Identification Support Plate-Replacement Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7541 2/24/1997	Service Bulletin - Turbofan Engine-Upper Towershaft Bearing Housing- Replacement Of			X			
7548 11/4/1997	Service Bulletin - Turbofan Engine-Oil Pump Assy- Replacement/Modification Of			X			
7549 R1 9/25/1997	Service Bulletin - Turbofan Engine-Gearbox Input Drive Spacer-Replacement Of			X			
7564 5/6/1999	Service Bulletin - Turbofan Engine-Towershaft- Replacement Of			X			
7565 5/5/1999	Service Bulletin - Turbofan Engine-Upper Tower Shaft Duplex Bearing- Replacement Of			X			
7567 R1 7/7/2000	Service Bulletin - Turbofan Engine-Igniter Box Grounding Strap-Introduction Of			X			
7577 7/12/2001	Service Bulletin - Turbofan Engine-Lower Lcf Life Impellers-Introduction Of			X			
7581 7/15/2002	Service Bulletin - Turbofan Engine-Introduction Of New Non-Cleanable Filter Element Option			X			
7585 7/5/2002	Service Bulletin - Turbofan Engine-Fuel Control Unit-Replacement Of			X			
7588 R2 1/24/2013	Service Bulletin - Turbofan Engine-Accessory Gearbox Input Drive Gear- Replacement/Modification Of			X			
7589 R1 5/15/2003	Service Bulletin - Turbofan Engine-High Turbine Disc Balancing Assembly- Replacement Of			X			
7601 2/16/2005	Service Bulletin - Turbofan Engine- New Protective Shipping Closure-Introduction Of			X			
7607 11/9/2006	Service Bulletin - Turbofan Engine-Fuel Control Ratio Lever-Inspection Of			X			
7618 R1 3/6/2008	Service Bulletin - Turbofan Engine-No. 4 Bearing Sleeve, Housing Assembly And Rotor Air Seal- Replacement/Modification Of			X			
7620 4/18/2008	Service Bulletin - Turbofan Engine-Low Pressure Turbine Disk-Inspection/ Replacement Of			X			

Category: Engine

Manufacturer: Pratt & Whitney Canada

Model: JT15D-4D

P/N:

S/N:

5/30/2014

SB # Eff. Date	Description	Complied Date & Time	Amendment Number Method of Compliance / Applicability	One Time	Recurring	Next Due	Authorized Signature & Number
7623 R1 3/5/2009	Service Bulletin - Turbofan Engine-High Turbine Shaft-Replacement/Modification Of			X			
7625 R1 11/26/2010	Service Bulletin - Turbofan Engine-Gasket- Replacement Of			X			
7627 3/5/2012	Service Bulletin - Turbofan Engine-Low Pressure Turbine Interstage Rotor Air Seal And Rotor Air Seal- Replacement Of			X			
7633 9/24/2012	Service Bulletin - Turbofan Engine-Retaining Ring-Alternate Source			X			
A7614 10/23/2007	Service Bulletin - Turbofan Engine-Igniters- Inspection Of			X			